CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	ECOLI	TEMP	pH
Feyrer Park Bridge	6/6/2007	1.22	2.0	N/D	49.5	13.9	7
50ft Upstream Of Outfall	6/6/2007	1.08	2.2	N/D	51.2	14.1	6.9
50ft Downstream Of Outfall	6/6/2007	1.21	2.2	N/D	53.8	14.1	7.0
Highway 211 Bridge	6/6/2007	1.22	2.6	N/D	74.9	13.9	6.8
IRRIGATION DITCH							
Feyrer Park Bridge At Irrigation Ditch	6/8/2007	0.63	1.8	N/D	28.8	13.0	6.4
Pipe Crossing At Irrigation Ditch	6/8/2007	0.87	2.6	N/D	55.6	12.9	6.3
N/D = Nondetectable							