CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	ECOLI	TEMP	pH
Freyer Park Bridge	10/10/2007	0.41	1.4	N/D	73.8	11.9	6.8
50ft Upstream Of Outfall	10/10/2007	0.49	1.0	N/D	26.9	12.0	6.9
50ft Downstream Of Outfall	10/10/2007	0.65	1.2	N/D	33.6	12.0	6.9
Highway 211 Bridge	10/10/2007	0.52	1.2	N/D	17.3	12.3	6.9
IRRIGATION DITCH							
Freyer Park Bridge At Irrigation Ditch	10/12/2007	0.68	1.6	N/D	22.6	10.7	6.8
Pipe Crossing At Irrigation Ditch	10/12/2007	0.70	1.4	N/D	27.5	11.2	6.8