CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	ECOLI	TEMP	pH
Freyer Park Bridge	10/17/2007	0.78	1.6	N/D	18.3	9.6	6.8
50ft Upstream Of Outfall	10/17/2007	0.67	1.2	N/D	33.1	9.6	6.9
50ft Downstream Of Outfall	10/17/2007	0.68	1.4	N/D	23.3	9.6	6.9
Highway 211 Bridge	10/17/2007	0.71	1.4	N/D	29.5	10	6.8
IRRIGATION DITCH							
Freyer Park Bridge At Irrigation Ditch	10/19/2007	2.4	31.1	N/D	42.6	10.7	6.5
Pipe Crossing At Irrigation Ditch	10/19/2007	1.6	27.7	N/D	35.9	10.8	6.6