

CITY OF MOLALLA  
 WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

<b>MOLALLA RIVER</b>	<b>DATE</b>	<b>BOD</b>	<b>TSS</b>	<b>NH3</b>	<b>ECOLI</b>	<b>TEMP</b>	<b>pH</b>
Feyrer Park Bridge	4/2/2008	0.57	0.6	N/D	11.0	4.8	6.9
50ft Upstream Of Outfall	4/2/2008	0.50	0.8	0.1	7.5	4.8	7.0
50ft Downstream Of Outfall	4/2/2008	0.47	0.8	0.1	9.7	4.8	7.0
Highway 211 Bridge	4/2/2008	0.57	1.2	0.3	10.9	5.2	7.0
<b>IRRIGATION DITCH</b>							
Feyrer Park Bridge At Irrigation Ditch	4/4/2008	0.34	1.4	N/D	7.4	6.7	7.0
Pipe Crossing At Irrigation Ditch	4/4/2008	0.54	1.8	N/D	60.2	6.8	6.9
<b>N/D = Nondetectable</b>							