

CITY OF MOLALLA
 WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	ECOLI	TEMP	pH
Feyrer Park Bridge	4/9/2008	0.35	1.2	N/D	15.6	6.5	7.0
50ft Upstream Of Outfall	4/9/2008	0.40	1.4	N/D	13.2	6.5	6.9
50ft Downstream Of Outfall	4/9/2008	0.39	1.6	N/D	13.2	6.6	7.0
Highway 211 Bridge	4/9/2008	0.56	1.6	N/D	21.6	6.9	7.0
IRRIGATION DITCH							
Feyrer Park Bridge At Irrigation Ditch	4/11/2008	0.24	2.4	0.1	9.6	6.6	6.6
Pipe Crossing At Irrigation Ditch	4/11/2008	0.37	3.0	0.1	39.3	6.4	6.8
N/D = Nondetectable							