

CITY OF MOLALLA  
 WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

<b>MOLALLA RIVER</b>	<b>DATE</b>	<b>BOD</b>	<b>TSS</b>	<b>NH3</b>	<b>ECOLI</b>	<b>TEMP</b>	<b>pH</b>
Feyrer Park Bridge	3/5/2008	0.45	1.2	N/D	6.3	4.8	6.7
50ft Upstream Of Outfall	3/5/2008	0.28	1.2	N/D	7.2	4.9	6.6
50ft Downstream Of Outfall	3/5/2008	0.30	1.2	N/D	3.1	4.9	6.6
Highway 211 Bridge	3/5/2008	0.32	1.4	N/D	7.3	4.9	6.6
<b>IRRIGATION DITCH</b>							
Feyrer Park Bridge At Irrigation Ditch	3/7/2008	0.19	1.2	N/D	7.4	5.9	6.8
Pipe Crossing At Irrigation Ditch	3/7/2008	0.34	1.0	N/D	7.3	6.0	6.8
<b>N/D = Nondetectable</b>							